

CERTIFICATE OF COMPLIANCE

Certificate Number E55996
Report Reference E55996-20180711
Issue Date 2023-JUNE-27

Issued to: IDEC CORP
6-64 NISHIMIYAHARA 2-CHOME
YODOGAWA-KU, OSAKA 532-0004 JAPAN

This certificate confirms that representative samples of SWITCHES, INDUSTRIAL CONTROL - COMPONENT
See Addendum page for Models/Product

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 508 & CAN/CSA C22.2 No. 14-18 - Industrial Control Equipment

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E55996
Report Reference E55996-20180711
Issue Date 2023-JUNE-27

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Industrial Control Switches:

RN2S-NL-A24, RN2S-NL-A115, RN2S-NL-A220, RN2S-NL-A230, RN2S-NL-A240, RN2S-NL-D12, RN2S-NL-D24, RN2S-NL-D48, RN2S-NL-D110, RN4S-NL-A24, RN4S-NL-A115, RN4S-NL-A220, RN4S-NL-A230, RN4S-NL-A240, RN4S-NL-D12, RN4S-NL-D24, RN4S-NL-D48, RN4S-NL-D110, RN2S-CL-A24, RN2S-CL-A115, RN2S-CL-A220, RN2S-CL-A230, RN2S-CL-A240, RN2S-CL-D12, RN2S-CL-D24, RN2S-CL-D48, RN2S-CL-D110, RN4S-CL-A24, RN4S-CL-A115, RN4S-CL-A220, RN4S-CL-A230, RN4S-CL-A240, RN4S-CL-D12, RN4S-CL-D24, RN4S-CL-D48, RN4S-CL-D110, SJ1S-21L, SJ2S-21L, RN2S-L-A24, RN2S-L-A115, RN2S-L-A220, RN2S-L-A230, RN2S-L-A240, RN2S-L-D12, RN2S-L-D24, RN2S-L-D48, RN2S-L-D110, RN4S-L-A24, RN4S-L-A115, RN4S-L-A220, RN4S-L-A230, RN4S-L-A240, RN4S-L-D12, RN4S-L-D24, RN4S-L-D48, RN4S-L-D110.

RN2S-NF-D12, RN2S-NF-D24, RN2S-NF-D48, RN2S-NF-D110, RN2S-NF-A24, RN2S-NF-A115, RN2S-NF-A220, RN2S-NF-A230, RN2S-NF-A240, RN4S-NF-D12, RN4S-NF-D24, RN4S-NF-D48, RN4S-NF-D110, RN4S-NF-A24, RN4S-NF-A115, RN4S-NF-A220, RN4S-NF-A230, RN4S-NF-A240, RN2S-HNL-D12, RN2S-HNL-D24, RN2S-HNL-D48, RN2S-HNL-D110, RN2S-HNL-D220, RN2S-HNL-A24, RN2S-HNL-A115, RN2S-HNL-A220, RN2S-HNL-A230, RN2S-HNL-A240, RN4S-HNL-D12, RN4S-HNL-D24, RN4S-HNL-D48, RN4S-HNL-D110, RN4S-HNL-D220, RN4S-HNL-A24, RN4S-HNL-A115, RN4S-HNL-A220, RN4S-HNL-A230, RN4S-HNL-A240, RN2S-SNL-D12, RN2S-SNL-D24, RN2S-SNL-D48, RN2S-SNL-D110, RN2S-SNL-D220, RN2S-SNL-A24, RN2S-SNL-A115, RN2S-SNL-A220, RN2S-SNL-A230, RN2S-SNL-A240, RN4S-SNL-D12, RN4S-SNL-D24, RN4S-SNL-D48, RN4S-SNL-D110, RN4S-SNL-D220, RN4S-SNL-A24, RN4S-SNL-A115, RN4S-SNL-A220, RN4S-SNL-A230, RN4S-SNL-A240,

Accessory Relay Sockets –

SJ1S-05BS, SJ2S-05BS.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

